EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1		(701/100).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/01/30 18:48
L2	342	(700/37).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/01/30 18:48
L3	4313	(60/39.281).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/01/30 18:48
L5	1165	(318/561).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/01/30 19:39
L6	124	(60/238).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/01/30 18:53
L8	5160	l1 or l2 or l3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON ·	2007/01/30 19:40
L9	52	l8 and @pd>"20060802"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON .	2007/01/30 19:40
S2	2	"5197280" and acceleration	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/01/25 13:49

EAST Search History

S3	5214	acceleration and gas adj turbine	US-PGPUB;	OR	ON	2007/01/25 13:56
			USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB			
54	15	measure adj acceleration and gas adj turbine	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/01/25 14:04
S5	33	(measure with (acceleration and temperature)) and gas adj turbine	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/01/25 16:06
S6		(measure with (acceleration and temperature)) and gas adj turbine and gain	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/01/25 14:05
S9	0	(measure with (acceleration and temperature)) and gas adj turbine and carpernter	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON ·	2007/01/25 14:38
S14	0	COMPENSATED ADJ ERRROR ADJ SIGNAL	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/01/30 18:45
S15	214	COMPENSATED ADJ ERROR ADJ SIGNAL	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR .	ON	2007/01/25 18:12
S16	111	COMPENSATED ADJ ERROR ADJ SIGNAL AND GAIN	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON .	2007/01/25 18:19

Page 2